


Safety Warning

- Glass and aluminium can potentially cause injury. Please ensure you wear protective goggles, gloves, headgear and suitable foot-wear when assembling and glazing the building.
- Please remember that glass is fragile and should be handled with extreme care. Always clear up and dispose of any breakages immediately.
- In windy conditions please make sure that your cold frame is anchored down properly and that the vents are closed to minimise the chances of damage!

Additional Considerations

- You will find it helpful to prepare a large, clean and clear area in which to work in. A garage floor or flat lawn area is ideal.
- Most parts are numbered and can be identified by a stamp or removable label. Alternatively, the components can be identified by lengths detailed in the packing list (see diagram opposite).
- The 4' cold frame is used primarily as an example throughout this manual. The 6' components are referred to in each section and they are fitted in a similar manner to the 4'.























Part num	Section	Size (mm)	2 4	2 6	
957	L	574	2		
576			4	1	
579			4	1	







Part num	Section	Section Size (mm)		2 6
962	引起	425	2	3
574			2	3
589	M6x24mm		2	3
586	0		4	6













Part num	Section	Size (mm)	2 4	2 6
121	Т	612	2	3
123		612	2	3
124	Ţ	610	4	6
858		588	4	6
D	610 X 610	(see diag)	2	3
576			8	12
579			8	12
572				














436 Cold frame packing List



No	mm	4'	6'	
121	612	2	3	
123	612	2	3	
124	610	4	6	
950	1240	2		
951	1860		2	
952	1240	1		
953	1860		1	
954	1240	1		
955	1860		1	
956	580	2	2	
957	574	2	2	
958	510	2	2	
959	510	1	2	
960	460	2	2	
961	460	1	2	
962	425	2	3	
576	M6x10mm	28	36	
579	M6	28	36	
589	M6x24mm	2	3	
586	0	4	6	
574	<u></u>	2	3	
300	8	4	4	
580		4	6	
856	458	6	8	
857	508	6	8	
858	588	4	6	
572	15000	1 roll	1 roll	
573		4	4	